[Three] Examples of Ferroresonance in Distribution Systems

Roger C. Dugan Sr. Consultant Electrotek Concepts, Inc.

Examples


 Shopping Mall Incident
 Single-Phasing Distributed Generation
 Delta-connected Padmount Transformers on 12 kV



Shopping Mall Incident

34.5 kV distribution system

- "Power Surge" & Noisy Transformer
- Paint on top bubbled, charred
- Transformer tested OK
- Root Cause: Automobile accident
- Failures:TVSS in mall registers, etc
- 3-phase load likely tripped




Distributed Generation Interconnection requirements conflict DG must have separate transformer DG must separate at first sign of trouble If trouble is a blown riser pole fuse, unloaded transformer yields ideal

Same issue in modern commercial buildings

ferroresonance condition


Solutions


Three-phase switchgear at riser pole
Too expensive for small generators
Recommendation: No fuses between substation and 3-phase DG
3-phase reclosers or sectionalizers
Replace cutouts with solid blade Potentially detrimental to PQ




12 kV Padmounts...

- Ferroresonance less likely at 12 kV than at 25 or 35 kV
- Grd Wye-wye transformers the norm at 25 and 35 kV
- Many utilities continue to use deltaconnection in 12 kV systems without many known problems







Corrective Measures

- 3-phase switchgear
- Open or close all three cutouts as
 - simultaneously as possible
- Ensure the transformer is loaded while being switched.
- Eliminate fuses
- Prevent inadvertent fuse operation
 - Animal guards, etc.