


- Three-Phase Transformers


Mork

All of these can and are used to indicate the same winding connections:


IEEE Stds:




One-Line:



schematic




circuit 3-line diagram




In Europe and much of the world:

IEC Stds:

Dyn11



One-Line:



'old-down' diagram

